

MID AMERICA



MOTORWORKS

Pursue your passion here

**Suggested Installation Instructions for:
609-529, 1978-1982 Underhood Release Cable Installation**

This cable is very easy to replace, see diagram. Cable may require repositioning of pull cable at adjustment plate (perforated metal plate at cable end). We recommend you tie a temporary release wire or rope on each side of latch until cable is properly adjusted.

