


Mid America Motorworks VW Speedometer Cable Tech Tips

If your **VW Speedometer** has stopped completely, first test the speedometer head to see if it has frozen and broken your cable. To test the speedometer head: First, unscrew the cable at the speedometer head. Then, insert a small screwdriver in to the head socket and rotate it to see if it turns freely. If it's frozen, you must replace the speedometer before you replace the speedometer cable.

It is recommended to grease the cable before installing it. This will also help eliminate the "bounce" sometimes noted in the **Air Cooled VW's**.

A common symptom of VW Speedos is a vibration or flicker of the needle. This is often caused not by the speedometer or cable but by the square hole in the Front Wheel Bearing grease cap being worn or out of true. The SKUs for these are **396-184** and **354-426**.

Do not forget the circlip on the end of the speedo cable: **375-578**. **MAM**



Speedometer Cable.
Item # 313-218



Front LH Wheel Bearing
Cap with Hole.
Item # 396-184

Grease Cap
for Front Axle.
Item # 354-426



Quarter Window Latch
& Speedometer Cable,
Retaining Clip.
Item # 375-578

