




VW Beetle Luggage Panel Repair Tech Notes

Tech Note: Have a Beetle that the center part of the luggage repair panel is ok but the outer ends are rusted? We have a product that will make an effective repair without removing the entire luggage panel. Item number 321-192 is an outer repair section that will cover about 7 1/4" of the outer sides of the luggage panel and include about 3 1/2" of the inner fender at the highest point. Don't forget the seam sealant 106-016.

Tech Note: Watch out when cutting out the old sections of the luggage panel if you have an **Auto-Stick VW**. One of the main transaxle/torque converter fluid supply hoses sets directly under the driver side luggage panel. If you look close in this picture you can see where the cable goes into the back firewall. **MAM**



Luggage Compartment Shelf,
Rear, Repair Section.
(Drivers side or Passenger side)
Item # 321-192

Auto Seam Sealant Tube, 11 oz.
Item # 106-016

